IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re: Black et al.

U.S. Patent No.: 7,510,699 B2

Application No.: 10/779,907

Issued: March 31, 2009

Filed: February 17, 2004

Confirmation No: 8994

Title: IN VIVO FLUORESCENCE SENSORS, SYSTEMS, AND RELATED METHODS

OPERATING IN CONJUNCTION WITH FLUORESCENT ANALYTES

June 8, 2009

Commissioner for Patents

Attn: Certificate of Correction Branch

P.O. Box 1450

Alexandria, VA 22313-1450

REQUEST FOR ENTRY OF CERTIFICATE OF CORRECTION UNDER No. 35 U.S.C §254 AND 37 C.F.R. §1.322

Sir:

The Assignee of record for the above-referenced patent hereby requests, pursuant to 35 U.S.C §254 and 37 C.F.R. §1.322, that a Certificate of Correction be issued. This request is made in order to correct the mistakes incurred through the fault of the U.S. Patent and Trademark Office. The mistakes appearing in the patent are set forth with corrections on the Certificate of Correction enclosed herewith.

No fee is believed due. However, the Commissioner is authorized to charge any deficiency or credit any overpayment to Deposit Account No. 50-0220.

Respectfully submitted,

Julie H. Richardson Registration No. 40,142

Myers Bigel Sibley & Sajovec, P.A. P. O. Box 37428, Raleigh, NC 27627

Telephone: (919) 854-1400 Facsimile: (919) 854-1401 Customer No. 20792

CERTIFICATION OF ELECTRONIC TRANSMISSION

I hereby certify that this correspondence is being transmitted via the Office electronic filing system in accordance with §1.6(a)(4) to the U.S. Patent and Trademark Office on June 8, 2009.

Jessica M. French

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO.

7,510,699

APPLICATION NO.:

10/779,907

ISSUE DATE:

March 31, 2009

INVENTOR(S) :

Black et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Page 3, Foreign Patent Documents:

Please correct "WO98/43701 8/1998"

To read -- WO98/43701 10/1998 --

In the Claims:

Column 41, Claim 59, Line 23:

Please correct "configured to excitation" to read -- configured to emit an excitation --